

# Work Order ID 76519

**\*76519\***

Page 1

November-16-11 12:02:44 PM

Item ID: D2662-2 Accept **\*N900040100\*** Setup Start **\*NS1\***  
 Revision ID: Stop **\*NS2\***  
 Item Name: Saddle, RH In 206

Start Date: 11/16/11 Start Qty: 3.00 **\*3\*** Cust Item ID:  
 Required Date: 11/17/11 Req'd Qty: 3.00 **\*3\*** Customer: CU-DAR001

Reference: RMA RA111291 - RETURN

Approvals: Process Plan: *W* Date: Tooling: Date: Run Start **\*NR1\***  
 QC: Date: SPC (Y/N): Date: Stop **\*NR2\***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D2662	Rev D

100

0.00

**\*100\***

QC

Quality Control

Memo

INSPECT RA111291

0.00

*Schedule*

*374482*

*+3*

110

0.00

**\*110\***

Packaging

Packaging

Memo

RE-IDENTIFY USING NEW B/N

0.00

*11/16/11 BD*

120

QC21- Final Inspection - Work Order Release

0.00

**\*120\***

QC

Quality Control

Memo

0.00

*11/16/11*

*11-16-11 (3)*



# Picklist Print

November-16-11 12:02:44 PM

Page 1

Work Order ID: 76519

Parent Item: D2662-2

Start Date: 11/16/11

Required Date: 11/17/11

Parent Item Name: Saddle, RH In 206

Start Qty: 3.00

Required Qty: 3.00

Comments: IPP: C00.11.01Removed P/O for Powder Coat - in house processEC  
IPP Rev:D As per Rev D 07-03-19 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2662-2		Manufactured	No				Each	25.0000		3			
Saddle, RH In 206													

Location	Loc Qty	Loc Code
ST429	10	
73852	10	
ST435	15	
73853	15	

1-79482  
1-74484  
1-75118

h



**RA 1 1291 D2661/D2662**

**SADDLES**

**NCR11-935**

Received @ Dart November 11<sup>th</sup>, 2011  
Inspected @ Dart November 16<sup>th</sup>, 2011

**Instructions for RA 111291 D2661/D2662 Saddles**

- Qty X 34 saddles were returned
- **Following are to be SCRAPED**
  - D2662-2 B11028 QTY X 4, B9043 QTY X 2, B9042 QTY X 3
  - D2661-1 B64559 QTY X 5
  - D2661-2 B9913 QTY X 1, B10476 QTY X 3, B10015 QTY X 1, B10016 QTY X 1
- Need a work order to scrap
- **Following are to be returned to STOCK**
  - D2662-2 B74482 QTY X 1, B74484 QTY X 1, B75118 QTY X 1
  - D2662-1 B73846 QTY X 2
  - D2661-1 B73839 QTY X 4
  - D2661-2 B74475 QTY X 4
- Need a separate work order for each model to return back in to stock
- D2662-2 B74483 was dropped by DS needs to be striped then assed by QC and if not damaged to be re powder coated and put back in to stock under a new BATCH #

Keep

✓ 76516 - D2661-1	4	73839
✓ 76517 - D2661-2	4	74475
✓ 76518 - D2662-1	2	73846
✓ 76519 - D2662-2	3	1-74482 1-74484 1-75118

Scrap

5	- 64559
6	1-9913 3-10476 1-10015 1-10016
7	
8	
9	4-11028 2-9043 3-9042

76520 ✓  
76521 ✓  
76522 ✓  
76523 ✓

